

# RSFlite Public Manifest

October 13, 2023

## **2023-10-14 RSFlite 4.5.5**

### **New Features**

**4774** Probe and wedge database updated. It fixes some dimensions.

**4793** 128E WP2 utprobes and examples files have been added.

**4726** HV Calibration Improvement.

### **Known Issues**

**4689** The numeric keypad does not appear in the auto-hide menu mode.

## **2023-01-17 RSFlite 4.5.4**

### **New Features**

**4680** Improve HV error management

### **Fixed Issues**

**4684** Fix missing translations

## **2022-11-26 RSFlite 4.5.3**

### **New Features**

**4619** Correct HV error message to reduce confusion

**4600** Improve HV error management

**4634** Change in UT Filters specification

## **2022-03-17 RSFlite 4.5.2**

### **New Features**

None, follows other products' software version ID.

### **Known Issues**

**4547** The touchscreen may stop working when a VNC session has been closed.

## **2021-10-22 RSFlite 4.5.1**

### **New Features**

None, follows other products' software version ID.

## **Known Issues**

**4547** The touchscreen may stop working when a VNC session has been closed.

## **2021-10-12 RSFlite 4.5.0**

### **New Features**

**4461** New X6BW flat .utwedge files.

**4471** New StarTech WiFi dongle support.

**4535** There are new X2B probes and wedges.

### **Fixed Issues**

**4208** The RSflite could crash when the user clicks the "Next Index" software button.

**4364** The part overlay "W" shortcut is fixed.

**4366** Focus goes to the menus once you loaded a probe or a wedge.

## **Known Issues**

**4547** The touchscreen may stop working when a VNC session has been closed.

## **2021-04-07 RSFlite 4.4.0**

### **New Features**

**4115** New touchscreen and keypad

**4144** Improved Touchscreen Response

**4308** New Xpair update

### **Fixed Issues**

**3687** New probe in UTstudio+ have all elements activated by default

**3694** TCG is not reset when the start path is moved beyond the first point

**3717** TCG curve interpolation improvement when a TCG point is outside of the scan

**4223** Pulse width value of the MSEB4 probe has been updated.

## **2020-09-01 RSFlite 4.3.0**

### **New Features**

**3790** Chinese language have been improve for RSflite

**3804** RSflite can now generate Merge C-Scan

**3926** Touchscreen Sensitivity to change the colour palette has been improved

**3930** The welcome screen has been refurbished and is now offering the User's Template concept.

**3933** New layout with B-scan have been added

**4092** For conventional UT configuration the T-loss functionality is now available for DAC/TCG calibration

### **Fixed Issues**

**3701** Layout A-L-C Amp-C Depth is now showing the proper view

## **2020-01-24 RSFlite 4.2.6**

### **New Features**

None, follows other products' software version ID.

### **Known Issues**

**3638** Alphabetic Keypad in lieu of Numeric Keypad for some parameters

## **2019-06-21 RSFlite 4.2.4**

### **New Features**

None

### **Fixed Issues**

**3706** Internal tools enhancement

### **Known Issues**

**3638** Alphabetic Keypad in lieu of Numeric Keypad for some parameters

## **2019-03-28 RSFlite 4.2.3**

### **New Features**

None

### **Fixed Issues**

**3692** Internal tools enhancement

### **Known Issues**

**3638** Alphabetic Keypad in lieu of Numeric Keypad for some parameters

## **2019-03-12 RSFlite 4.2.2**

### **New Features**

None, follows other products' software version ID.

### **Known Issues**

**3638** Alphabetic Keypad in lieu of Numeric Keypad for some parameters

## **2018-11-22 RSFlite 4.2.1**

### **New Features**

**3494** Translation file for French, Chinese, Slovak, Czech, Russian

## **2018-10-17 RSFlite 4.2.0**

### **New Features**

None, follows other products' software version ID.