



## 2012-10-19 RapidScan2 Release Manifest V5.3.4.9

### Featuring:

- Addition of Ranking function, sold as an option
- Addition of Bounding ratio, sold as an option
- Addition of JPEG saving capability
- Addition of Report function

### Fixed:

- #3681-Application doesn't respond anymore when click on Color map graph.
- #3357-New C-Scan is cause the software to exit (found on v5.3.4.6)
- #3135-When starting New C-A-B scan views are blank.
- #3132-Color Map problem on version 5.2.16
- #3793-Some saved jpeg images are distorted
- #3682-Print to pdf bounding ratio not well displayed.
- #3625-c-scan sample in T-scan rotated 90 degrees and then rotated back to 0 degree again may cause system freeze
- #3607-Error conversion when select Menu C-scan sub-menu in imperial.
- #3591-Import New doesn't reload correctly A-scan's Range.
- #3578-missing customized colour map cause loading scan data failed and system cause the software to exit
- #3454-bonding ratio not accurate as empty space should not count
- #3428-Application not responding anymore when starting a new c-scan
- #3373-Rapidscan not responding switching menu Evaluation in T-scan.
- #3136-Colour bar next to the gate number control doesn't match with the Gate in control
- #3128-Colour map editor, the text on the axis on the bottom colour bar does not read correctly
- #3117-2D scan height scale incorrect when it is loaded in offline mode
- #3604-Chinese minor missing word translated.
- #3590-Button Save Image doesn't work.
- #3582-Reload data are not completed successfully
- #3574-Error when importing a 3D setup when we have Rapidscan 2
- #3120-Protection warning memory message doesn't pop up and application cause the software to exit in Rapidescan3D.
- #3374-Ctrl-I cause the software to exit on large TIFF when cscan is very long, i.e. 100M
- #3125-Test T-Scan size properties in Imperial units
- #3262-F1 help message box not appear on offline mode in c-scan
- #3477-2D scan direction can be switch between top-down and left-right

### Known issues:

- Not Applicable
- #3096 - A-log and Panel's name aren't correctly displayed when viewing it. Masterscan Only
- #3773- More than 104 A-Scan require more time to connect to D-20+, connection fail
- #3666- transfer Inspection Plans from PC to DFD. First one has been transferred without any problems. Each next is overwriting on this first one.

## Hardware and Software Compatibility Matrix ([2 Configurations supported](#))



#### Dell Precision M4600 (Preferred)

- Window XP SP2 (32 bit)
- Video Card Nvidia Quadro M2000 driver version 6.14.12.7536
- RapidScan 3D v5.3.4.9
- RapiDAQ\_v522 driver version 1.0.5.22
- FaroArmUsb 5753\_32bits driver version 5.7.5.34
- Faro Advantage Arm Firmware version 155
- Faro Fusion or Platinum only works on 224

#### HP Elitebook 8540p

- Window XP SP2 (32 bit)
- Video Card Nvidia NVS 5100M driver version 6.14.12.6128
- RapidScan v5.3.4.9
- RapiDAQ\_v522 driver version 1.0.5.22
- FaroArmUsb 5753\_32bits driver version 5.7.5.34
- Faro Advantage Arm Firmware version 155.
- Faro Fusion or Platinum only works on 224